

LICENSED CONSTRUCTION SUPERVISOR DISCIPLINARY ACTIONS

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Michael T. Rogers 110 Seneca Street Lowell, MA 01852	69236	<u>License Revoked</u> effective August 28, 2000. May apply for reinstatement of license after 1 year and must re take CSL examination in order to regain license.
Thomas Dixon 9 Ice Pond Road Attleboro, MA 02703	75037	<u>License Revoked</u> effective August 28, 2000. May apply for reinstatement of license after 1 year and must re take CSL examination in order to regain license.
Len Gibely 149 Main Street Peabody, MA 01960	59482	Letter of <u>Reprimand</u> Issued and placed on licensee's file.

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Roger Gagnon, Sr. 15 Mann Street Bellingham, MA	29073	<u>License suspended</u> for 6 MONTHS effective October 17, 2000. Licensee may re-apply after 6 months on condition that all code violations have been corrected
John M. Daniels 155 Lanesboro Rd. Cheshire, MA	29491	<u>License suspended</u> for ONE YEAR effective October 17, 2000. Licensee may re apply for license after one year and after successfully passing the Construction Supervisor License Examination
Edward Faneuf 21 South Main Street Templeton, MA	56550	<u>License suspended</u> for a minimum of 3 MONTHS effective October 17, 2000. Licensee may re-apply after 3 months on condition that all code violations have been corrected LICENSE REINSTATED
Wayne Whatmough 470 Towne Street North Attleboro, MA	21319	<u>License suspended</u> indefinitely effective October 17, 2000. Licensee may apply for reinstatement after all work performed and approved by local building department and after licensee has successfully passed the Construction Supervisor License Examination.

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Philip Sirois, Jr. 243 Main Street Amesbury, MA	63707	<u>License suspended</u> indefinitely effective November 28, 2000 – must contact License Review Committee prior to reinstatement
Brian Jamieson 4051 Center Street RFD #2 Palmer, MA	69772	<u>License suspended</u> until code violations corrected – effective November 28, 2000
Dean Todd PO Box 2020	45717	<u>License suspended</u> for TWO YEARS effective November 28, 2000 - must contact license review committee as a condition of

Lanesboro, MA		reinstatement.
---------------	--	----------------

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Dean Martin	38684	License Suspended 6 months effective January 23, 2001 and must pass construction supervisor license examination prior to reinstatement <Currently Under Appeal>
Carl D. Corrinine	060845	Letter of Warning issued. Licensee also must correct all drainage problems at the subject site.
Gary Edwards	060163	License Revoked January 23, 2001. Must seek permission of the BBRS prior to being allowed to apply for reinstatement.
Peter Montesanti	75129	License Suspended one year effective January 23, 2001 and must pass construction supervisor license examination prior to reinstatement.

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Robert Jepson	39359	License Suspended effective April 26, 2001, and must take and pass construction supervisor license examination prior to reinstatement.
William Penny	30574	License Suspended effective April 26, 2001, and must take and pass construction supervisor license examination prior to reinstatement
Andrea Hadaya	70113	Letter of Warning Issued. Licensee must obtain permit for work performed and if allowed by homeowner, must return to correct problems at subject site.

<u>Licensee</u>	<u>CSL #</u>	<u>Disciplinary Action Taken</u>
Glen Field	59267	License Suspended effective June 19, 2001, must take and pass construction supervisor license examination. Must see the Board Administrator prior to reinstatement.
Kris LeGrand	35948	Letter of Reprimand issued effective June 19, 2001.
Woodrow Witter	34246	Letter of Warning Issued effective June 19, 2001. Warning also applies to a second complaint currently on file with the BBRS. Any future complaints will result in further disciplinary action before the License Review Committee.
Arthur Muller	66722	License Suspended effective June 19, 2001, must take and pass construction supervisor license examination. Must see the Board Administrator prior to reinstatement.

Updated June 26, 2001